

APPEARANCE® 25 High Solids Floor Finish



- Outstanding Initial Gloss And Film Clarity
- Excellent Leveling Properties
- Extremely Durable In High Traffic Conditions
- Works In Any Maintenance System

PRODUCT AVAILABILITY:

- 9651.....4/1 gal.
- 9655.....1/5 gal. pail
- 96555.....1/55 gal. drum

FULLPRO FULLER PROFESSIONAL

PRODUCT DESCRIPTION: Appearance® 25 is a high solids floor finish that rapidly builds gloss with minimal coats. This acrylized formulation produces a clear, color-free, high-gloss finish that works well in a variety of maintenance programs. Appearance® 25 produces a star-like shine when burnished. For use on vinyl composition, vinyl, rubber, asphalt, concrete, terrazzo, linoleum, rubber and sealed wood floors.

FEATURES:

Durable:

Exceptional resistance to heel marking, scuffing and repeated scrubbing with detergents means that **Appearance® 25** outwears conventional finishes. Both stripping and recoating cycles are extended, lowering the frequency of these costly procedures.

High Solids Formula:

Maximum labor productivity is assured as gloss builds quickly, with fewer coats.

Superior Soil Resistance:

The tough film of **Appearance® 25** minimizes soil penetration and surface abrasion even under extreme conditions. Autoscrubbing easily picks up dirt, immediately restoring the shine.


Versatility:

Maintain **Appearance® 25** using many recognized methods, spray buff, top coat or scrub/recoat.


PRODUCT SPECIFICATIONS:

pH	9.0 ± 0.3
Appearance	Off White Emulsion
Fragrance	Mild polymeric
Freezing Point	About 32°F
Non-Volatile Solids	25.35 ± 0.35
% Total Solids	30.80
Boiling Point	212°F
Solubility in Water	Dispersible
Flash Point	None to Boiling
Coverage	2000 to 2500 sq. ft. per gallon
(may vary due to differences in porosity of the surface)	

INITIAL APPLICATION



MAINTENANCE



DIRECTIONS FOR USE:

INITIAL APPLICATION

1. **REMOVE** old sealer/finish using a FullPro stripper and following label directions.
2. **APPLY** a thin coat of **Appearance® 25** using a clean finish mop.
3. **DRY:** Allow 20-30 minutes drying time.
4. **APPLY** 2-3 coats for best results allowing for adequate drying time between each coat.

MAINTENANCE

1. **DUST MOP** the floor. Remove gum, labels, and other attached soil deposits with a long-handled scraper or putty knife.
2. **DAMP MOP OR AUTOSCRUB** using a FullPro cleaner and following the label directions.
3. **BURNISH** the floor with a high speed machine and appropriate pad.